Case Study no. 9 – Supporting Cleansing of a Third-Degree Burn Wound of the Upper Leg

Patient
82-year-old patient.

Clinical
Third-degree burn wound to the upper leg following a thermal injury.

Challenges
Required effective yet controlled wound cleansing to reduce infection risk while protecting vulnerable surrounding tissue.

Brush Solution
Balanced cleansing that allowed thorough hygiene over a larger wound surface without excessive mechanical stress.

Clinical Outcomes & Rationale
Balanced cleansing across a larger wound surface ensured effective hygiene while avoiding excessive mechanical stress. This supported a clean wound environment and prepared the wound for further therapeutic interventions.

"Effective cleansing, even in extensive burn wounds."



21/07/2025



7/08/2025



25/08/2025



09/09/2025